

Lucrari Planificate zilnic de la Sector Canal – 11 Aprilie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Zimbrului,Volga,T.Sperantia,Vagonului - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Dealului,Plugului -curatat GS	66 rao Popovici	Bara,Teodoru		Teh.Patcas A
3	Moliere - -curatat CM Slatinei - curatat GS	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sanmartin,Mierlei,O.Ghibu,Bumbacului - curatat CM	BH-83-RAO-Lucaciu	Paul V Paul A	Reclamatie consumator	Ing Coldea E
2	Lunga 1/A, H.Coanda,P.Ispirescu - curatat CM	BH-13 CAO-Craciun	Buzas	Reclamatie consumator	Ing.Coldea E
3	Onestilor D29-D31;PB 50-54 + Gradinita ,Banatului 2 T Vladimirescu - curatat CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Olteniei,Avram Iancu,Gr Ureche,Vaporului,T Vladimirescu -vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Aluminei A6 ,Calea Santandreiului,Calea Aradului, S.M.Klein - vid retea menaj	BH-O9- Ban	Balas	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Alesdului /Tileagdului	38 rao	Montat rac nou 1 buc	Sala Sziskai	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Clujului 227	38 rao	Rep camin vizitare	Burca,Budureanu,	Ing Coldea E

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

Sef Mal Sting: **ing Coldea Eugen****MAL DREPT****a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Olteniei, P-ta Bucuresti 6 - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Aluminei A6, Aleea Rogerius L1-G6 - curatat CM	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Olteniei	45 rao	Curatat CM	Oros, Groza Uivarosi	ms.Hamza
3	P-ta Bucuresti 6	45 rao	Curatat CM	Sav,Fuzi	ms.Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d. Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------