

**Lucrari Planificate zilnic de la Sector Canal**  
**Data: 17.04.2012**

## MAL STANG

### Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Ep I .Alexe,A.Pavel Banut,Bunytai Vincze,Stejarului - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Tusnadului,Tarnavelor,C Negruzi.Lisabonei -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Caporal Gh Musat- - curatat GS Sovata D32-33,Gradinarilor x1 -Curatat CM	29 rao Balaj I	Nagy, Demian		Teh.Patcas A

### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Bumbacului,Onisifor Ghibu,Penes Curcanul - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Horea 45,P-ta Independentei - curatat CM	BH-13 CAO-Craciun	Buzas	Reclamatie consumator	Ing.Coldea E
3	Cazaban,Mestesugarilor,Salcamilor,Onestilor, - curatat CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	T Vladimirescu, Pop de Basesti, Kogalniceanu, Costaforu, Calea Aradului -vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea Santandreiului, Selimbarului, Al Rogerius -vid retea menaj	BH-09- Ban	Balas	Reclamatie consumator	Ing Coldea E

**d. Lucrari de reparatii canalizare menajera ,colector menajer, si camine de vizitare:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Horea 45	45 rao	Rep rac menaj	Sala ,Sziskai, Budureanu, Burca	Ing Coldea E

**e. Rep racord pluvial si Guri de scurgere –retea pluviala**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f. Refacere cu beton**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

## MAL DREPT

**b) Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Selimbarului F7-F10 - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Alumnei D 3, Dacia C5-C7 - curatat CM	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

**c) Lucrari de reparatii canalizare menajera, camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Selimbarului F6 F9	45 rao	Curatat -CM	Oros, Sav,	ms.Hamza
3	B-dul Dacia C5-C7	45 rao	Curatat -CM	Fuzi , Groza Uivarosi	ms.Hamza

**Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**e.Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------