

Lucrari Planificate zilnic de la Sector Canal
Data: 18.04.2012

MAL STANG

Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Academiei,Bicazului,Cometei,Bucegi,Ingusta,N.Iorga - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Alesdului,Campului,Dlfinului -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Doina,Balcescu - curatat GS Selimbarului 6-F9 -Curatat CM	29 rao Balaj I	Nagy, Demian		Teh.Patcas A
4	Aluminei B1, .A1,Cazaban P 55 -Curatat CM	45 RAO Urs			Ing Coldea E

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	BumvAPORULUI 21,Bumbacului/Al Zidarilor - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Razboieni,t2-t6,Gradinarilor x3-x6 - curatat CM	BH-13 CAO-Vidican	Bohos	Reclamatie consumator	Ing.Coldea E
3	Bumbacului/Al Zidarilor,Cazaban,S.M.Klein, - curatat CM	BH-72-RAO-Tautu	Marchis	Reclamatie ,consumator	Ing Coldea E

c. Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Pop de Basesti, ,Olteniei,Splaiul Crisanei -vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Calea Santandreiului, Kogalniceanu, Costaforu -vid retea menaj	BH-09- Zglibolt	Lazar	Reclamatie consumator	Ing Coldea E

d. Lucrari de reparatii canalizare menajera ,colector menajer, si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Mierlei 5	45 rao	Rep camin vizitare menaj	Budureanu, Burca	Ing Coldea E

e. Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Horea 45	45 rao	Ref cu beton	Sala ,Sziskai	Ing Coldea E

MAL DREPT**b) Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Olteniei - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Alumnei D 3, Dacia C5-C7 - curatat CM	BH-12-Demian	Ciarnau	Reclamatie consumator	Ing Bonta

--	--	--	--	--	--

c) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Selimbarului F6- F9	45 rao	Curatat -CM	Fuzi , Groza Uivarosi	ms.Hamza
3	Olteniei	45 rao	Curatat -CM	Oros, Sav,	ms.Hamza

Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

e.Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
--------	--------	--------	-------------------	-----------	----------

Toate lucrarile dupa orele 15.00 vor fi coordonate de catre inginerul sau maistrul de serviciu dupa masa

BH- 22- RAO -Braica

BH –23- RAO –Boglut

BH- 56- RAO- Balan

BH-66- RAO –Popovici

BH –29- RAO – Balaj I