

## Lucrari Planificate zilnic de la Sector Canal

### a. Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Cantemir,CET 2, -curatat G.S Galileo Galilei X7	56rao-BI	Daraban L,Bara		Teh.Patcas
2	REVIZIE	66rao -PP	Gal,Teodoru,Naghi		Teh.Patcas

### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Ciheiului PB 52-54,Matei Basarab-Zoo,Gr Ureche bl 19,Seleusului 13 T1-curatat CM/GS	BH-83-RAO-Lucaci	Paul A	Populatia + conducere	Ing Coldea
2	Onestilor A5,Cantemir - curatat CM/GS	BH-13 CAO-Silaghi	Marchis	Populatia + conducere	Ing Coldea
3	Doina PB101,Odobescu,Decebal/Negruzzi- curatat CM/GS	BH-72-RAO-Tautu	Bernat	Populatia + conducere	Ing Coldea

### c.Vidanjat retea canalizare menajera si pluviala( lucrari

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Matei Basarab-Gradina Zoo,Calea Santandreiului-vidanjat retea CM /CP	BH-54-RAO-Muresan	Iuhas	Populatia + conducere	Ing Coldea
2	Santului,Gh Doja 129,Al Rogerius L1-L3- vidanjat retea CM /CP	BH-09-Chisvasi	Balas		Ing Bonta
3	Cicero,Costaforu,Kogalniceanu,Razboieni T2- vidanjat retea CM /CP	BH-71-Tirtea I	Cicas,G		

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	M.Basarab –Gradina Zoo	38 rao	Rac canal nou	Budureanu,Sziskai,Sala	Ing Coldea

**e.Rep racord pluvial si Guri de scurgere**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f.Refacere pavaje lucrari**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

**e )Curatat canal menajer**

Nr.crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde
--------	----------------------	--------	-----------	---------------	----------

**MAL DREPT:****b)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Defect	BH-43-Rao		Populatia + conducere	Ing Bonta
2	Fagului PC 74,Er Necunoscut- curatat CM/GS	BH-12-Urs	Marchis		Ing Bonta

**c)Lucrari de reparatii canalizare menajer,camine,**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Sfantul Apostol Andrei PB 14	38rao	Rep camin de vizitare menajer	Oros,Buzas,Uivarosi	Ms Hamza

**Reparati racord pluvial si G.S**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

•  
**Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Iza S1	38rao	Refacere cu beton	Rotaru,Groza	Ms Hamza
2	Corneliu Coposu QR59	38rao	Refacere cu beton	Toie	Ms Hamza