

## Lucrari Planificate zilnic de la Sector Canal – 02 iulie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Cele 3 Crisuri,Aleea Gojdu,Spiru Haret -curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Avram Iancu,Col. Buzoianu,Muscatei -curatat GS	66 rao Popovici	Bara, Gal		Teh.Patcas A
3	Galileo Galilei,Hortensiei -curatat GS	45rao Silaghi	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Leoneredo da Vinci /Paraul Adona,Cicero,Gradinarilor 32 - curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Santandrei - curatat CM/GS	BH-13 CAO-Vidican	Marchis	Reclamatie consumator	Ing.Coldea E
3	P-ta 1 Decembrie,Cicero,Calea Aradului,D4- curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Cicero,Costaforu,Kogalnicean,Decebal 29,Gradinarilor 32 -vid retea menaj /pluviala	BH-54-RAO-Muresan	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului,Aleea RogeriusDacia Zig-Zag -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

<b>Nr.</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
------------	---------------	---------------	------------------------------	------------------	-----------------

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

<b>Nr crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Calea Aradului D4		Rep rac pluvial +gs	Buzas,Burca	Ing Coldea E

**f. Refacere cu beton**

<b>Nr. crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
----------------	---------------	---------------	------------------------------	------------------	-----------------

## **MAL DREPT**

**a)Desfundat canale :**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Transilvaniei ,Posada langa Master -curatat CM/GS	BH-43-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Er. Necunoscut,Dacia pasaj Zig Zag - curatat GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

**b) Lucrari de reparatii canalizare menajera, camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Pascal DP 72	38 rao	Rep.camin	Ciarnau,Uivarosi	ms.Hamza

**c) Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Dacia Zig –Zag	38 rao	Rep canal pluvial	Toie,Buzas,Oros	ms.Hamza

**d.Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	V.Babes 1	38rao	Compactat,turnat beton	Sav,Groza,Ciarnau,Uivarosan	