

## Lucrari Planificate zilnic de la Sector Canal - 9 iulie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Crangului,Lugojului,Privighetorii -curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Oct .Goga -curatat GS	66 rao Popovici	Bara, Gal		Teh.Patcas A
3	Zalaului,Otelarilor,Pavel Banut-curatat GS	45rao Silaghi	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	C-tin Tanase,Gradinarilor,Leonardo da Vinci,Ov .Densusanu,AN196- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Sanmartin - curatat CM/GS	BH-13 CAO-Vidican	Marchis	Reclamatie consumator	Ing.Coldea E
3	Gh Doja 26,Delavrancea 12,- curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Cicero,Costaforu,KogalniceanuDelavrancea 12,Arany Ianos 2 Decebal 29 -vid retea menaj /pluviala	BH-54-RAO-Muresan	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului,Aleea Razboieni,Gh Doja,Delevrancea 12-vid retea menaj/pluviala	BH-09- Zglibolt	Lazar	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	C-tin Tanase 6	25 roa	Rep rac menaj	Buzas,Burca, Iuhasz	Ing Coldea E

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f. Refacere cu beton**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Biruintei 55	25 roa	Refacere cu beton	Budureanu ,Balas	Ing Coldea E

## MAL DREPT

**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
2	Er .Necunoscut –Fantana ,Pavel Banut 8,Bicazuli,Praporgescu - curatat GS/CM	BH-12-Demian	Fuzi	Reclamatie consumator	Ing Bonta

**b)Lucrari de reparatii canalizare menajera,camine,**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Gh Doja 13	38 rao	Montat camin	Ciarnau,Sav,Groza	Ing Bonta

**c)Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d)Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Roman Ciorogariu 51	38rao	Refacere cu beton	Sav,Groza,Ciarnau,Uivarosan	Ing Bonta
2	Moscovei 2		Refacere cu beton		Ing Bonta