

## Lucrari Planificate zilnic de la Sector Canal – 16 iulie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	N.teclu,Ion Vidu,Tr Vuia,Iosif Vago -curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Barcaului -curatat GS	66 rao Popovici	Bara, Gal		Teh.Patcas A
3	Iasomieii,Penes Curcanul,Q28-29 -curatat GS	45rao Urs	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	,Penes Curcanul,Q28-29 Razboieni - curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Stelutei 31,Ion Vidu,Tr Vuia- curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	Matei Corvin,Spartacus - curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Cicero,Costaforu,Kogalniceanu,Arany Ianos 2-vid retea menaj /pluviala	BH-54-RAO-Muresan	Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului,Spartacus Matei Corvin -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Pitestilor 10	38.rao	Rep rac menaj	Budureanu, Burca Buzas Iuhasz	Ing Zetocha

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f. Refacere cu beton**

Nr .crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

Sef Mal Sting: **ing Coldea Eugen**

## MAL DREPT

**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Er.Necunoscut , Dacia C7-C5 - curatat GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta
<b>2</b>	<b>DEFECT</b>	<b>BH -73 RAO</b>			
<b>3</b>	<b>DEFECT</b>	<b>BH -71 RAO</b>			

**b)Lucrari de reparatii canalizare menajera,camine,**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Spartacus 28-30	38 rao	Ridicat la cota cm	Ciarnau .Groza ,Sav	Ing Bonta

**c)Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Republicii 63	38 rao	Rep gura scurgere	Buzas,Toie	Ing Bonta

**d)Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------