

## Lucrari Planificate zilnic de la Sector Canal

Data: 26.07.2012

### MAL STANG

#### Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari Sovata -rigole -curatat GS	56rao Balan	Teodoru ,Daraban G		Teh.Patcas A
2	Sifonari ,Sovata -rigole -curatat GS	66 rao Popovici	Gal ,Teodoru		Teh.Patcas A
3	Lucrari	45rao Urs C	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Borsului 45,Cantemir D33-D31,Lugojului 4- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	Independentei /1 Decembrie - curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	Matei Corvin-Transoil - curatat CM/GS	BH-72-RAO- Tautu	Bernat	Reclamatie consumator	Ing Coldea E
4	Ursului/OctGoga,Dacia ,Decebal - curatat CM/GS	BH-43 –RAO-Chisvasi	Rotaru	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Beiusului 45,Cantemir D33-31,Lugojului4,- -vid retea menaj/pluviala	BH-54-RAO-Muresan	Iuhasz	Reclamatie consumatr	Ing Coldea E
2	Republicii-Mag.Crisul-Pazaj,,Matei Corvun -PECO -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E
3	Pandurilor/Moliere,Cicero.Kostaforu	BH-71-RAO-Tartea	Cicas,Lazau	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	D.Cantemir D33-D31	45 rao	Curatet CM	,Burca	Zetocha

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde

**f. Refacere cu beton**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Arany Ianos 2	45 rao	Refacere cu beton	Balas,	Zetocha

**Sef Mal Sting: ing Coldea Eugen**

## MAL DREPT

**b)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde

2	Stefan cel Mare AN41-42,Dunarii-Clasicor - curatat GS/CM	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta
---	--	------------	------------	-----------------------	-----------

**c)Lucrari de reparatii canalizare menajera,camine,**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Aleea Salca X3	45 rao	Rep canal col	Buzas,Budureanu	Ing Bonta

**Reparati racord pluvial ,guri de scurgere –retea pluviala45 rao**

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Republicii 10	45 roa	Rep rac pluvial	Buzas,Toie ,Sav Ciarnau,	Ing Bonta

**e.Refacere cu beton**

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
--------	--------	--------	-------------------	-----------	----------

Toate lucrarile dupa orele 15.00 vor fi coordonate de catre inginerul sau maistrul de serviciu dupa masa

BH- 22- RAO –Sav BH –23- RAO –Boglut BH- 56- RAO- Balan, BH-66- RAO –Popovici, BH –45- RAO – Urs

Sef Mal Drept : **Dumitru BONTA**

Sef Sector Canal :

Ing Stefan ZETOCHA