

## Lucrari Planificate zilnic de la Sector Canal – 8 Iunie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sf Apostol Andrei- curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Sf Apostol Andrei -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Graurilor,Morii x27,Margaretei 32 - curatat CM	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Nufarului,-Proges,Mestesugarilor - curatat CM/GS	BH-83-RAO-Lucaciu	Paul V,Paul A	Reclamatie consumator	Ing Coldea E
2	D.Cantemir,Selesului,Eftimie Murgu - curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	Nufarul –Proges,Mestesugarilor - curatat CM/GS	BH-72-RAO-Tautu	Bernat	Reclamatie consumator	Ing Coldea E

#### c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Kogalniceanu,Pop de Basesti,Costaforu,-vid retea menaj /pluviala	BH-54-RAO-Silaghi	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului Nufarului-vid retea menaj/pluviala	BH-09- Urs	Popa	Reclamatie consumator	Ing Coldea E

**d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Nufarul -Proges	38 rao 25roa	Rep camin menaj	Balas Sala,Sziskai Burca,Bohas Iuhasz	Ing Coldea E

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f. Refacere cu beton**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

## **MAL DREPT**

**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sf Apostol Andrei - curatat /suflat GS/CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Babe –CARPO,Uzinelor,Aluminei A6-curatat CM/GS	BH-12-Duma	Buzas	Reclamatie consumator	Ing Bonta

**b)Lucrari de reparatii canalizare menajera,camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Ec Teodoroiu 66	38 rao	Rep canal menaj	Groza,Oros ,Ciarnau	ms.Hamza

**c)Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d)Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Ady Endre 14	38 rao	Refacere cu beton	Sav,Buzas Uivarosi	ms.Hamza