

## Lucrari Planificate zilnic de la Sector Canal – 20 Iunie 2012

### MAL STANG

#### a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Emil Palade -curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Sucevei -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Penes Curcanul -curatat GS ,Cazaban P38-39,Ady Endre 7,T Vladimirescu1- curatat CM	45 rao Silaghi	Nagy, Demian		Teh.Patcas A

#### b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Onisifor Ghibu,Penes Curcanul,P-ta Ferdinand- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V,Paul A	Reclamatie consumator	Ing Coldea E
2	Santandrei - curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	Cazaban X1B,P39P38,Sucevei,12 Octombrie- curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

#### c)Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	P-cul Balcescu,Costaforu.Kogalniceanu,Cicero,T Vladimirescu 1- bl Stea,Decebal 29,Arany Ianos 2 -vid retea menaj /pluviala	BH-54-RAO-Muresan	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului P-cul Balcescu,Aleea Rogerius -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E

**d) Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

<b>Nr.</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	12 octombrie 5	38 rao	Rep rac menaj –Utilitati	Burca	Ing Coldea E

**e.Rep racord pluvial si Guri de scurgere –retea pluviala**

<b>Nr crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Anatole France /Industriei		Rep gura scurgere	Sala, Balas	Ing Coldea E

**f. Refacere cu beton**

<b>Nr. crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	Gutemberg 17		Refacere cu beton	Iuhasz.Burca	Ing Coldea E

## **MAL DREPT**

**a) Desfundat canale :**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Dacia C5-C7,Sf Apostol Andrei C30	BH-43-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Ady Endre 7,Aleea Rogerius E2 ,-curatat GS	BH-12-Duma	Buzas	Reclamatie consumator	Ing Bonta

**b) Lucrari de reparatii canalizare menajera, camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	P-ta Ferdinand	38 rao	Rep rac menaj	Sav, Ciarnau	ms.Hamza
2	Aluninei 13 D64	38 rao	Rep rac menaj	Oros ,Buzas,Uivarosi	ms.Hamza

**c) Reparati racord pluvial ,guri de scurgere –retea pluviala**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d) Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------