

Lucrari Planificate zilnic de la Sector Canal – 22 Iunie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,Crisului,Er Grigore, -curatat GS	56rao Balan	,Daraban G		Teh.Patcas A
2	Sifonari,Scurta,Semenicului,Magurei -curatat GS	66 rao Popovici	Gal.Bara		Teh.Patcas A
3	Ialomitei,Selimbarului,Progresului,-PB9 ,Tr Lalescu PC 54 –CM,Sovata c19 -cm- curatat CM	45 rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Scoalelor27/A,Marasesti 12,- curatat CM/GS	BH-83-RAO-Lucaciu	Paul V,Paul A	Reclamatie consumator	Ing Coldea E
2	Santmartin - curatat CM/GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing.Coldea E
3	Ady Endre 7, Matei Corvin –Interoil -taxare- curatat CM/GS	BH-72-RAO-Tautu	Bohos	Reclamatie consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	P-cul Balcescu SPAU,Costaforu.Kogalniceanu,Cicero, Fagerului 16/L-taxare -vid retea menaj /pluviala	BH-54-RAO-Muresan	Cicas Lazau	Reclamatie consumatr	Ing Coldea E
2	Calea Aradului,Calea Santandreiului P-cul Balcescu SPAU, Decebal 23 -vid retea menaj/pluviala	BH-09- Ban	Popa	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Lucian Blaga 16	45 rao	Rep canal colector	Burca ,Iuhasz	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Biruintei 27/A	45 rao	Rep racord pluvial	Sala, Balas	Ing Coldea E

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
----------------	---------------	---------------	------------------------------	------------------	-----------------

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sovata, C4,Sovata C18-19,Progresului PB 9	BH-43-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Er .Necunoscut-fantana,Galileo Galilei,Q9,Tr Lalescu PC 54 ,-curatat GS	BH-12-Duma	Buzas	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Ady Endre 53	38 rao	Rep rac menaj	Sav, Ciarnau, Uivarosi, Groza	ms.Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
1	Aluninei 13 D64	38 rao	Refacere cu beton	Oros Buzas, Toie	ms.Hamza