

Lucrari Planificate zilnic de la Sector Canal – 29 Mai 2012

MAL STANG

a. Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Calea Clujului - curatat GS	56rao Balan	Daraban L ,Daraban G		Teh.Patcas A
2	Calea Clujului -curatat GS	66 rao Popovici	Bara, Paul A		Teh.Patcas A
3	Decebal,Sovate,Nufarul - curatat GS	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

b) Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Averescu 45,Liszt Ferencz,Al Vlahuta - curatat CM	BH-83-RAO-Lucaciu	Paul V	Reclamatie consumator	Ing Coldea E
2	DEFECT	BH-13 CAO-		Reclamatie consumator	Ing.Coldea E
3	Iuliu Maniu 31 - curatat CM/ GS	BH-72-RAO-Mierlut C	Temciuc	Reclamatie ,consumator	Ing Coldea E

c. Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	,Kogalniceanu, Costaforu,Pop de Basesti-vid retea menaj	BH-54-RAO-Muresan	Cicas	Reclamatie consumatr	Ing Coldea E
2	Aleea Rogerius L1-L3, Calea Aradului ,Calea Santandrei.,Milcovului-vid retea menaj	BH-09- Urs	Popa	Reclamatie consumator	Ing Coldea E
3	Calea Clujului- suflat GS	BH-43- RAO-Tautu	Bernat	Reclamatie consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

N r.	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Onestilor R 61	38 rao	Rep camin vizitare menaj	Sala ,Sziskai,	Ing Coldea E
2	Onisifor Ghibu QB3	38 rao	Montat camin vizitare	Bohos ,Burca, Iuhasz,Buzas	Ing Coldea E

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

MAL DREPT**a)Desfundat canale :**

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sovata,Sf Apostol Andrei - curatat/suflat GS	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Gen. Magheru M 12- curatat CM/GS	BH-12-Duma	Derecichei	Reclamatie consumator	Ing Bonta

b)Lucrari de reparatii canalizare menajera,camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	t.Vladimirescu 60 /A	38 rao	Rep rac menaj	Oros Toie Buzas,Groza	ms.Hamza

c)Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d)Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
1	Feleacului 10	38 rao	Ref cu beton	Sav ,Buzas M ,Uivarosi	ms.Hamza