

Lucrari Planificate zilnic de la Sector Canal – 23 Martie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,Nicolae Soga -curatat GS	56rao Braica	Daraban L ,Daraban G		Teh.Patcas A
2	Sifonari ,Teiului - curatat GS	66 rao Popovici	Bara,Teodoru ,Gal,		Teh.Patcas A
3	Milcovului D54,Ghioceilor 8-curatat CM Cvartal Transilvaniei –curatat CM	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Hategului,Ghioceilor,Nufarului,- curatat CM	BH-83-RAO-Lucaciu	Paul V Paul A	Reclamatie consumator	Ing Coldea E
2	Averescu,D.Zamfirescu,Cantemir curatat CM	BH-13 CAO-Vidican	Marchis	Reclamatie consumator	Ing Coldea E
3	Nufarului,D122,Onisifor Ghibu curatat CM	BH-72-RAO-Tautu	Bernat	Reclamati ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Ghioceilor,Mestesugarilor,Pop de Basesti ,Sntandreiului ,Costaforu,Horea,Nufarului -vid retea menaj	BH-54-RAO-Muresan	Cicas, Lazau	Reclamatie consumatr	Ing Coldea E
2	Kogalniceanu,Seleusului,Lamaitei,Fagului/Aluminei.Milcovului - vid retea menaj	BH-09- Zglibolt	Lazar	Reclamati consumator	Ing Coldea E

d. Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Horea 39	38 rao	Rep caminVizit	Sziskai,Sala, Balas	Ing Coldea

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	D.Zamfirescu 3	38 rao	Montat sifon pardosea -CP	Sziskai ,Burca	Ing Coldea E

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Al Calinului X1	38 rao	Refacere cu beton si borduri	Budureanu ,Iuhasz,Bohos	Ing Coldea E

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Lamaitei ,Selimbarului - curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Al Rogerius L1, .G6,N3.N7 - curatat CM	BH-12-Demian	Buzas	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Selimbarului F7-F9/Transilvaniei	45 rao	Periat- CM	Uivarosi, Buzas, Derecichei	Ms Hamza
2	Lamaitei 9	45 rao	Rep rac menaj	Oros, Toie, Ciarnau	Ms Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------