

Lucrari Planificate zilnic de la Sector Canal – 28 Martie 2012

MAL STANG

a)Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Onisifor Ghibu ,cvartal Onisifor Ghibu -curatat GS	56rao Braica	Daraban L ,Daraban G		Teh.Patcas A
2	St cel Mare,cvartal blocuru Stefan cel Mare - curatat GS	66 rao Popovici	Bara,Teodoru ,Gal,		Teh.Patcas A
3	Slatinei PC 16-17 -curatat CM Cvartal bl Decebal –curatat GS	29 rao Silaghi	Nagy, Demian		Teh.Patcas A

b)Desfundat canale :

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Calea Aradului –ERA SHOPING -taxae- curatat CM	BH-83-RAO-Lucaciu	Paul V Paul A	Reclamatie consumator	Ing Coldea E
2	Apateului PB 103 - curatat CM +GS	BH-13 CAO-Craciun	Temciuc	Reclamatie consumator	Ing Coldea E
3	Calea Aradului Pp62, -CM, SovataQ2 Deceba - curatat GS	BH-72-RAO-Tautu	Bernat	Reclamati ,consumator	Ing Coldea E

c.Vidanjat retea canalizare menajera si pluviala si lucrari .

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Apateului PB 103,Costaforu,Kogalniceanu,Calea Santandreiului-vid retea menaj	BH-54-RAO-Muresan	Cicas, Lazau	Reclamatie consumatr	Ing Coldea E
2	Olteniei 22-24,Al Rogerius L1L2L2-G6 Sovata Q2 -vid retea menaj	BH-09- Ban	Popa R	Reclamati consumator	Ing Coldea E

d.Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Apateului 16 PB 103	38 rao	Rep canal col menaj	Budureau ,Balas,Bohos,Burca	Ing Coldea

e.Rep racord pluvial si Guri de scurgere –retea pluviala

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	D.Zamfirescu 3	38 rao	Rep gura scurgere	Sala Sziskai, Iuhasz	Ing Coldea E
2	Decebal /Calarasilor 18	38 rao	Rep camin vizitare	Sala Sziskai, Iuhasz	Ing Coldea E

f. Refacere cu beton

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

Sef Mal Sting: **ing Coldea Eugen**

MAL DREPT

a)Desfundat canale :

Nr.crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Olteniei 22-24,Gh Doja 223- curatat CM	BH-73-Chisvasi	Rotaru.I,	Reclamatie consumator	Ing Bonta
2	Carpati 11 PB 4/21,Galileo Galilei R 2 - curatat CM	BH-12-Duma	Fuzi	Reclamatie consumator	Ing Bonta

b) Lucrari de reparatii canalizare menajera, camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
1	Ana Iparescu 19,19/A	45 rao	Montat racord nou	Oros Ciarnau ,Groza	Ms Hamza
2	Crangului 15	45 rao	Rep camin vizitare	Buzas Derecichei ,Uivarosi	Ms Hamza

c) Reparati racord pluvial ,guri de scurgere –retea pluviala

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------------	---------------	---------------	------------------------------	------------------	-----------------

d. Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------