

Lucrari Planificate zilnic de la Sector Canal – 01.02.2013

MAL STANG
ing Coldea Eugen

a) Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sextil Pscariu - curatat cm/gs	45RAO-Muresan	Bohos,Buzas,Lazau	Curatat gs cm	ing Coldea
2	Sifonari Mehedinti – curatat gs	66 Rao-Popovici	Gal, Bara	Curatat gs cm	Patcas
3	Sifonari,Alea Zidarilor Z1,Gradinarilor 16,Iuliu Hossu– curatat gs	29 RAO -Buzas	Demian ,Naghi		Patcas

b) Desfundat canale

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Sextil Puscariu Sc Gen 6,Gradinarilor 16,Av Iancu 2- curatat cm/gs	BH-83RAO-Lucaci	Paul,Balaj	Reclamatie /Dispecerat	ing Coldea
2	Defect	BH-13 CAO-		Reclamatie /Dispecerat	ing Coldea
3	SAALCAMILOR PB 140,Al Zidarilor Z1Nasaudului 6-8- curatat cm/gs	BH-72RAO-Craciun	Temciuc	Reclamatie /Dispecerat	ing Coldea
4	Sf Apostol Andrei Sovata PB 29-28Aluminei A5,A6 scA -curatat cm/gs	BH-73-RAOChisvasi	Rotaru,Paul	Reclamatie /Dispecerat	Ing Bonta
5	Oct Goga,,Calea Aradului -curatat gs	BH-43 CAO- Tautu	Bernat	Reclamatie /Dispecerat	ing Coldea

c) Vidanjat retea canalizare menajera si pluviala(lucrari)

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	Salcamilor pb 140.,Cicero,Santului,Al Rogerius,Calea Aradului,	54 RAO- Ban	Lazar,Burca	Reclamatie /Dispecerat	ing Coldea
2	DEFECT	BH-09- CAO ,		Reclamatie /Dispecerat	ing Coldea
3	Sextil Puscariu Sc Gen 6,Razboieni,Costaforu,Gradinarilor	71 RAO-Tartea	Iuihasz	Reclamatie /Dispecerat	ing Coldea

d) Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Sextil Puscariu Sc gen 6	23 rao+45 rao	Montat gs +rac plv	Sala Sziskai.Budureanu,	ing Coldea
2	Sextil Puscariu Sc gen 6	23 rao+45 rao	Curatat retea canal pluvial	Bohos,Lazau , Balaj, Buzas	ing Coldea

e) Rep racord pluvial si Guri de scurgere

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

f) Refacere pavaje lucrari

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

g) Curatat canal menajer

Nr. crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde
---------	----------------------	--------	-----------	---------------	----------

MAL.DREPT:
ing. Dumitru BONTA

a) Desfundat canale

Nr.cr	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Al Posada,Mehedinti - curatat cm/gS	BH-12- Duma	Derecichei	Reclamatie /Dispecerat	Ing Bonta

b) Lucrari de reparatii canalizare menajer,camine,

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde:
---------------	---------------	---------------	------------------------------	------------------	------------------

c) Reparati racord pluvial si G.S

Nr.crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	Aleea Posada/Al Rogerius	22 rao+38 rao	Rep gura scurgere	Ciarnau, , Oros	ing, Silaghi
2	Aleea Posada (Grad.nr 20)	22 rao+38 rao	Rep gura scurgere	Toie,Sav, Groza	ing, Silaghi

d) Refacere cu beton

Nr.crt	Strada	Masini	Refacere cu beton	Muncitori	Raspunde
---------------	---------------	---------------	--------------------------	------------------	-----------------

e) BLINDARI Canal menajer pentru neplata