

## Lucrari Planificate zilnic de la Sector Canal – 25 Februarie 2013

**MAL STANG**  
ing Coldea Eugen

### a) Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Sifonari,Mestesugarilor,Salcamilor,Lapusului- curatat cm/gs	66 RAO-Popovici	Demian,Bara,Teodoru,	Curatat gs cm	ing Coldea
2	Sifonari,Nufarului,D.Cantemir – curatat /gs	29 RAO –Buzas	Cicas, Bohos	Curatat gs cm	Patcas
3	D.Gherea 18/A,Lapusului X 104,C.Noica,Penes Curcanul	45 RAO-Urs			
4	-Lucrare	OR-2143-Chirila			

### b) Desfundat canale

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Tiglarilor 2B,O.Ghibu,Aleea Forajului,Bumbacului DN 52-64,Leonardo da Vinci,Sextil Puscariu-Sc Gen 6- curatat cm/gs	BH-83RAO-Lucaci	Paul,Balaj	Reclamatie/ Dispecerat	ing Coldea
2	Cantemir,Rosiorlor,C.Barnutiu .- curatat cm/gs	BH-13 CAO-Craciun	Buzas	Reclamatie/ Dispecerat	ing Coldea
3	C.Noica x26-AN 32,P.Curcanul x10-13,R16.Q7-Q9R12- curatat cm/gs	BH-72RAO-Muresan	Bernat	Reclamatie/ Dispecerat	ing Coldea
4	Lacul Rosu an 58-87,AN78 D79,QR59QR5,AN100-92, C.Coposu an19-an27- curatat cm/gs	BH-73RAO-Chisvasi	Rotaru		

**c) Vidanjat retea canalizare menajera si pluviala( lucrari)**

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	Kogalniceanu ,C.Aradului ,C.Santandreiului,Santului,Al Rogerius,- vidanjat reta cm/cp	54 RAO-Ban	Popa	Reclamatie /Dispecerat	ing Coldea
2	<b>DEFECT</b>	<b>BH-09- CAO ,</b>		Reclamatie /Dispecerat	ing Coldea
3	C.Noica x26-AN 32,P.Curcanul x10-13,R16.Q7-Q9R12,Cicero,Razboieni T2-vidanjat reta cm/cp	71 RAO-Tartea	Iuhasz	Reclamatie /Dispecerat	ing Coldea

**d) Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	C.Noica x26-AN 32,P.Curcanul x10-13,R16.Q7-Q9R12	23 rao+ 29rao	Curatat retea cm	Bohos Cicas	ing Coldea

**e) Rep racord pluvial si Guri de scurgere**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde`
1	D,Gherea 18/A	23 rao+45 rao	Rep racord pluvial gura de scurgere	Budurenu	ing Coldea
2	Lapusului X104	23 rao+45 rao	Rep racord pluvial gura de scurgere	Sziskai,Sala	

**f) Refacere pavaje lucrari**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

**g) Curatat canal menajer**

Nr. crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde
---------	----------------------	--------	-----------	---------------	----------

sofer –BH- 23 RAO- Naghiu I

**MAL.DREPT:**  
**ing. Dumitru BONTA**

**a) Desfundat canale**

<b>Nr.cr</b>	<b>Strada</b>	<b>Masini</b>	<b>Muncitori</b>	<b>Cine solicita</b>	<b>Raspunde</b>
1	Aluminei A6,Republici15,G.Calinescu An47,Aleea Rogerius L1-L3,Parcul Traian 29 - curatat cm/gS	BH-12- Duma	Derecichei	Reclamatie /Dispecerat	Ing Bonta

**b) Lucrari de reparatii canalizare menajer,camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Matei Corvin 209	22 rao+38 rao	Rep camin vizitare	Oros,Groza Paul	ing, Silaghi
2	Lacul Rosu an 58-87,AN78 D79,QR59QR5,AN100-92, C.Coposu an19-an27	22 rao+38 rao	Curatat retea cm	Toie,Ciarnau, Sav,Buzas	ing, Silaghi

**c) Reparati racord pluvial si G.S**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	------------------------------	------------------	-----------------

**d) Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------

**e) BLINDARI Canal menajer pentru neplata**