

## Lucrari Planificate zilnic de la Sector Canal – 19 Ianuarie 2013

**MAL STANG**  
ing Coldea Eugen

### a) Curatat Guri de scurgere

Nr crt	Strada	Masini	Muncitori	Nr guri de scurgere	Raspunde
1	Costaforu C9-C12,Cantemir D18D31Sextl P D 60,	45RAO-Tartea	Bohos,Buzas,Lazau	Curatat gs cm	ing Coldea
2	Spartacus x3,C.Coposu AN 29	66 Rao-Popovici	Gal.Naghi	Curatat gs cm	Patcas

### b) Desfundat canale

Nr crt	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	O.Ghibu x8,x9,Gr Ureche17-21.Bumbacului52-64,Leonardo da Vinci IalomiteiAN27 - curatat cm/gs	BH-83RAO-Lucaci	Paul V,Balaj	Populatia + conducere	ing Coldea
2	Rosiorilor ,Al Salca,Calea Aradului P59-P73- curatat cm/gs	BH-13 CAO- Craciun	Temciuc	Populatia + conducere	ing Coldea
3	Cantemir D58-31;Sex PPB 53,C23-D45- curatat cm/gs	BH-72RAO-Tautu	Bernat Iuhasz	Populatia + conducere	ing Coldea
4	Roman Ciorogariu/Academiei,Negruzi,Brancus,Balcescu -curatat cm/gs	BH-73-RAOChisvasi	Rotaru,	Populatia + conducere	ing Coldea

### c) Vidanjat retea canalizare menajera si pluviala( lucrari

Nr crt	Strada	Masini	Muncitor	Cine solicita	Raspunde
1	Cicero,Costaforu,Santului,Cazaban,Cantemin C1-C8,Calea Aradului,Aleea Rogerius,Spartacus X3,Razboieni T2,R,Ciorogariu/Academiei- cm/cp	54 RAO- Ban	Popa, Burca	Populatia+conducere	ing Coldea
2	<b>DEFECT</b>	<b>BH-09- CAO ,</b>			

**d) Lucrari de reparatii canalizare menajera ,colector menajer,si camine de vizitare:**

Nr .	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
1	D.Cantemir D58-D31,D60,Sextil p pb 63	22 rao+45 rao	Curatire retea cm	Sala Sziskai.Budureanu	ing Coldea
2	D.Cantemir C 25-D45	22 rao+45 rao	Curatire retea cm	Bohos,Lazau ,Buzas	ing Coldea
3	Costaforu C9-C12	22 rao+45 rao	Curatire retea cm	Bohos,Lazau ,Buzas	ing Coldea

**e) Rep racord pluvial si Guri de scurgere**

Nr crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
--------	--------	--------	-----------------------	-----------	----------

**f) Refacere pavaje lucrari**

Nr. crt	Strada	Masini	Lucrari ce se executa	Muncitori	Raspunde
---------	--------	--------	-----------------------	-----------	----------

**g) Curatat canal menajer**

Nr. crt	Nume prenume, adresa	Masini	Muncitori	Cine solicita	Raspunde
---------	----------------------	--------	-----------	---------------	----------

**MAL.DREPT:**

**ing. Dumitru BONTA**

**a) Desfundat canale**

Nr.cr t	Strada	Masini	Muncitori	Cine solicita	Raspunde
1	Dacia U2P-cul Bratianu SP,Spartacus x3,Coposu AN 19-27, curatat cm/gS	BH-12- Duma	Derecichei		Ing Bonta

**b) Lucrari de reparatii canalizare menajer,camine,**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde:</b>
1	Dacia U2	22 rao	Rep camin vizitare -descoperit	Uivarosi,Sav Ciarnau	ing, Silaghi

**c) Reparati racord pluvial si G.S**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Lucrari ce se executa</b>	<b>Muncitori</b>	<b>Raspunde</b>
1	R.Ciorogariu/Academiei	22 rao	Rep gura scurgere	Oros, ,Groza	ing, Silaghi

**d) Refacere cu beton**

<b>Nr.crt</b>	<b>Strada</b>	<b>Masini</b>	<b>Refacere cu beton</b>	<b>Muncitori</b>	<b>Raspunde</b>
---------------	---------------	---------------	--------------------------	------------------	-----------------

**e) BLINDARI Canal menajer pentru neplata**